

INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY



[A Division of NATRIP Implementation Society (NATIS), Govt. of India]

Non-Transferable

TEST REPORT

ULR No.: TC536021040000159F Test Report No.: C T 0 G Q 9 3 0 5 NAME AND ADDRESS OF THE:

CUSTOMER

Excellence

Service

nnovation

1.0

1.1

2.0

3.0

NAME AND ADDRESS OF THE:

MANUFACTURER

CUSTOMER LETTER REF

Date: 01.10.2021

M/s. Okaya Power Private Limited D-8 Udyog Nagar, Rohtak Road, New Delhi-110041

M/s. Sunoxx International

Vill. Panjhera, Nalagarh-Swarghat Road, Tehsil Nalagarh, Distt. Solan, Himachal Pradesh-174101

IOCS No. CCTNOKYAPBEEL85848 Dated - 20-Feb-2020

DESCRIPTION OF DEVICE LINDER TEST (DUT):

DUT Name	Battery module, 12 V
Battery Type	Lead Acid
Battery Capacity(Ah)	90Ah (Ah in 5 hrs)
Rated Voltage	12 V DC
ld/Model No.	OTER 16012
Quantity	06 Nos. of Battery module (ICAT/EEL/85848/01-06)
Trade Name	OKAYA
Drawing No.	DW-1042-00



4.0 DATE OF RECEIPT OF SAMPLE: 06.11.2020

5.0 CONDITION OF SAMPLE: No physical damage observed.

TEST OBJECTIVE: To validate the safety requirements of traction battery as per AIS:048:2009 with 6.0 amendment No.2 on 17.01.2020

7.0 TEST METHOD: Test method referred from AIS:048:2009 with amendment No.2 on 17.01.2020.

ANY DEVIATION OR EXCLUSION FROM TEST METHOD: No 0.8

FUNCTIONAL VERIFICATION: Functional verification done and battery module was found satisfactory. 9.0

CONCLUSION: The battery module specified in Sr.No.3.0 of this test report met all the test requirements 10.0 when tested as per AIS:048 as amended upto date as mentioned in Annexure-I of this report.

11.0 TEST DESCRIPTION: Please refer the Annexure-I of this report.

12.0 DATE OF PERFORMANCE OF TEST: Please refer the Annexure-I of this report.

TEST RESULTS: Please refer the Test requirements and Results in Annexure-I of this report. 13.0

14.0 LOCATION OF TEST: ICAT CENTRE-I.

Prepared By	Checked By		Approved By	*
Manish	Ser la constitución de la consti	THE FOR AUTOMORE THE PROPERTY OF THE PROPERTY		G09305
MANISH BERWAL Engineer	UDIT KAUL Dy. Manager	* MANESAR * LES	PAMELA TIKKU Sr. General Manager	Page 01 of 07 + Dwg. (01) [85848]

Office Address: Centre-I: Plot No.-26, Sector-3, HSIIDC, IMT-Manesar, Gurugram-122050. Haryana (India) Centre-II: Plot No.-01, Sector-M-11, HSIIDC, IMT-Manesar, Gurugram-122050. Haryana (India) Phone: 0124-4586111, Fax: +91-124-2290005. E-mail: team@icat.in, Website: <u>www.icat.in</u>

(An ISO 9001, ISO 14001 and ISO 45001 certified, scope wise NABL accredited and BIS recognised Test House)




ULR No.: TC536021040000159F Test Report No.: C T 0 G Q 9 3 0 5

Date: 01.10.2021

DISCLAIMER

- 1. ICAT issues Test reports/ Extension reports/ Developmental Reports for vehicles/ parts/ components/ assemblies etc. based on the documents produced and/or prototype / vehicle(s) or sample(s) submitted by the applicant and testing thereof.
- ICAT issues Test reports/ Extension reports/ Developmental Reports in compliance to Motor Vehicle
 Act/ Central Motor Vehicle Rules and their provisions as amended from time to time or any other
 statutory orders under which ICAT is authorized. Other Rules/Acts are outside the purview/scope of
 the Test reports/Extension reports/ Developmental test reports
- Test(s) on prototype/ vehicle(s)/ sample(s) is/are carried out on the basis of standard procedures as
 notified under specific rules/ requested by the applicant. Results of such tests are property of bearer
 of Test Reports/ Extension Reports / Developmental test reports. These results cannot be disclosed
 unless specifically so ordered by Government, Court, etc
- 4. Unless otherwise supported by a separate Certificate, this Test report Extension Reports / Developmental test reports shall not be considered in isolation as valid Type approval for any vehicle
- 5. ICAT is not responsible for testing each vehicles/ parts/assemblies etc. for which Test Reports/ Extension reports/ Developmental test reports is issued. Further, ICAT is not responsible for ensuring manufacturing quality of the vehicles/ components/ parts/ assembles etc. for which the Test Reports/ Extension reports/ Developmental test reports is /are issued.
- 6. ICAT is no way responsible for any misuse or copying any design/type/system in connection with entire vehicle/ components/parts and assemblies covered under the Test Reports/ Extension reports/ Developmental test reports is /are issued
- 7. Breach of any statutory provisions, of Indian laws or laws of other countries, will be sole responsibility of the customer. ICAT shall not be liable for any claims or damages made by the customer, whatsoever. The customer shall alone be liable for the same and undertakes to indemnify ICAT

 in this regard
- 8. Further, ICAT has the right, but not under obligation to initiate cancellation / withdrawal of the Test report/Extension/ Developmental test report is/are issued, in case of any fraud, misrepresentation, when it surfaces and comes in the knowledge of ICAT
- 9. No extract, abridgment or abstraction from this test report may be published or used to advertise the product without the written consent of the Director, ICAT, who reserves the absolute right to agree or reject all or any of the details of any items of publicity for which consent may be sought. The appropriate local court at Gurugram shall have the jurisdiction in respect of any dispute, claim or liability arising out of this report.





ULR No.: TC536021040000159F

Test Report No.: C T 0 G Q 9 3 0 5

Annexure-I

Date: 01.10.2021

TEST REQUIREMENTS AND RESULTS: 1.0

Cl. No.	Test	Test Description	Observations/Results
2.1 Electr	rical Tests		
2.1.1	Short Circuit test (Test ID:ICAT/ EEL /85848/01) Date of Test: 20.09.2021	Battery Module Condition: Fully charged (100% SOC), contained at ambient temperature. Apply a hard short in less than one second to the battery module with a conductor specified in the standard. Test Duration: 10 minutes, or until another condition occurs which prevents completion of test (i.e. component melting, etc.) Lab temperature: Not exceeding 30°C Acceptance Criteria: After 2 hours of observation: At the end of the test, there shall be no: a) Physical damage to the casing or mechanical parts. b) Melting of components. c) Fire or explosion. It is acceptable for the battery to become dry at the end of the test.	Ambient temperature : 25°C Conductor of ≤ 5mΩ was used and short was applied for 10 minutes. No physical damage, explosion or melting observed. Satisfactory.


Prepared By		Checked By	
Manish	THE FOR AUTOMORES STORES & STO	SP	
			Page 03 of 07
MANISH BERWAL		UDIT KAUL	Dwg(01)
Engineer		Dy. Manager	[85848]



Date: 01.10.2021

ULR No.: TC536021040000159F Test Report No.: C T 0 G Q 9 3 0 5

Temperature was 25°C Battery module **Over Charge test** was charged (Test ID:ICAT/ with 10 A for EEL /85848/02) 2.1.2 10 hours. Date of Test: Battery Module Condition: Fully charged (100% SOC), 20.09.2021 contained at ambient temperature at 27±5°C. No physical Duration: 10 hours damage, The battery is to be overcharged at a constant charging melting or current of 0.1 (C₁₀). explosion Acceptance Criteria: observed. At the end of the test, there shall be no: a) Physical damage to the casing or other mechanical Satisfactory. parts. b) Melting of components. c) Fire or explosion.



ULR No.: TC536021040000159F Test Report No.: C T 0 G Q 9 3 0 5 Date: 01.10.2021



2.2 Mechanical Tests

101

2.2.1 (Test ID:ICAT/ EEL /85848/03) Date of test : 08.09.2021

Vibration test

Battery Module Condition: Fully charged (100% SOC), contained at ambient temperature, firmly held on the vibration table in vehicle mounting position.

Vibration test will be carried out in three-axis viz. in the vertical axis, horizontal axis and battery positioned in longitudinal direction. Acceleration: 3 g (sinusoidal vibration)

Frequency: 30-150 Hz

Sweep rate: 1 octave per minute Duration: 2 hours in each axis

Immediately after the test, discharge the battery at room temperature not exceeding 30° C, at the rate of I = 0.2 x Battery capacity(C₅)

Acceptance Criteria:

During test, there shall be no electrolyte loss. The deterioration of battery rated capacity during discharging shall not be more than 10%. At the end of the test, there shall be no:

a) Physical damage to the casing or other

mechanical parts b) Fire or explosion Temperature was 25°C during test
No electrolyte loss observed during test.
Immediately after the test, battery was discharged at 18 A
And deterioration observed was not more than 10%.

No physical damage or explosion observed.

Satisfactory.

Prepared By

Checked By

Page
05 of 07

H
MANISH BERWAL
Engineer

Dy. Manager

Recked By

Date: 01.10.2021

ULR No.: TC536021040000159F Test Report No.: CT0GQ9305

nnovation • Service • Excellence

2.2.2

Shock test (Test ID: ICAT/ EEL /85848/04) Date of test: 09.09.2021

Battery Module Condition: Fully charged (100%) SOC), contained at ambient temperature not exceeding 30°C, firmly held on the vibration table in vehicle mounting position. Shock test will be carried out in three-axis viz. in the vertical axis, horizontal axis and battery positioned in longitudinal direction. Acceleration: 30 g (half-sine wave) No. of shocks: 10 in each axis Duration: 15 ms of each shock Immediately after the test, discharge the battery at room temperature, at the rate of I = 0.2 x Battery capacity(C₅)


Acceptance Criteria:

The deterioration of battery rated capacity during discharging shall not be more than 10%. At the end of the test, there shall be no: a) Physical damage to the casing or other mechanical parts b) Fire or explosion.

Temperature was 25°C during test Immediately after the test, battery was discharged at 18 A and deterioration observed was not more than 10%.


No physical damage or explosion observed.

Satisfactory.



ULR No.: TC536021040000159F Test Report No.: C T 0 G Q 9 3 0 5

Penetration Test (Test ID: ICAT/ EEL /85848/06) Date of test 21.09.2021 The battery Module shall be penetrated with a mild steel (conductive) pointed rod, which will be electrically insulated from the test fixture. The test will be carried out with 100% SOC of the Battery cell/Battery module. Rate of penetration: 8 cm/s. Diameter of Rod: 3mm/20mm Orientation of penetration: Perpendicular to the electrode plates. Minimum Depth of penetration: Through three cells or 100 mm The battery Cell should be observed, with the rod remaining in place, for a minimum of one hour after the test. Acceptance Criteria: At the end of the test, there shall be no: a) Melting of components. b) Fire or explosion. After penetration, up to a depth through module with a pointed mild steel rod of diameter 20mm, electrically insulated from the test fixture, no explosion, no fire and no melting observed. Satisfactory.	Steel (conductive) pointed rod, which will be electrically insulated from the test fixture. The test will be carried out with 100% SOC of the Battery cell/Battery module. Rate of penetration: 8 cm/s. Diameter of Rod: 3mm/20mm Orientation of penetration: Perpendicular to the electrode plates. Minimum Depth of penetration: Through three cells or 100 mm The battery Cell should be observed, with the rod remaining in place, for a minimum of one hour after the test. Acceptance Criteria: At the end of the test, there shall be no: a) Melting of components. After penetration, up to a depth through module with a pointed mild steel rod of diameter 20mm, electrically insulated from the test fixture, no explosion, no fire and no melting observed. Satisfactory.	2.2.3	Roll-Over Test (Test ID: ICAT/EEL/85848/05) Date of test: 20.09.2021	Rotate the battery module one complete revolution in one direction, for one minute in a continuous, slow-roll fashion, and observe leakage, if any. Then rotate the battery module in 90° increments in same direction for one full revolution. Hold the battery module for one hour at each position. Acceptance Criteria: The volume of electrolyte spilled in each position shall not be more than 25 ml per module.	Spillage observed was less than 25ml in each position. Satisfactory.
	Prenared Rv	2.2.4	(Test ID: ICAT/ EEL /85848/06) Date of test	steel (conductive) pointed rod, which will be electrically insulated from the test fixture. The test will be carried out with 100% SOC of the Battery cell/Battery module. Rate of penetration: 8 cm/s. Diameter of Rod: 3mm/20mm Orientation of penetration: Perpendicular to the electrode plates. Minimum Depth of penetration: Through three cells or 100 mm The battery Cell should be observed, with the rod remaining in place, for a minimum of one hour after the test. Acceptance Criteria: At the end of the test, there shall be no: a) Melting of components.	penetration, up to a depth through module with a pointed mild steel rod of diameter 20mm, electrically insulated from the test fixture, no explosion, no fire and no melting observed.



OKAYA POWER LTD REVISED BY DATE -TUBULAR 3.CAPACITY (Ah): 90Ah@C5 CORRECTED AT 30°C 4.TERMINAL POLARITY: RIGHT 5.SUITABLE APPLICATION: ELECTRIC VEHICLE DW-1042-00 000 NOTE CONTAINER MATERIAL : POLYPROPYLENE 1.TYPE OF BATTERY : LEAD ACID BATTERY 2.NOMINAL VOLTAGE :12 PART WEIGHT FINISHED BATTERY FOR OTER 16012 OVER ALL WIDTH = 172±3.0 DESCRIPTION SPECIFICATION NO.
SP.MS.1299 DESIGN DRAWN CHECKED APPROVED DATE SCALE PART MATL. PART NAME. UNSPECIFIED DRAFT ANGLE 15"-30" S
UNSPECIFIED AGDIS 0.2
ALL DIMENSIONS ARE IN mm
IF IN DOUBT PLEASE ASK
DO NOT SCALE THE DRG. \triangleleft 20-02-2026 1:1 0 M.SHETTY RAJESH RAJESH OVER ALL HEIGHT = 234±3.0 1800 103 7011 CANTHS AV Test. Rivert. No - CTOSIA 930 OVER ALL LENGTH = 408±3.0 • OKAY. 0 **TUBULAR BATTERY** E-RICKSHAW (3) **OTER 16012** HEIGHT UPTO TERMINAL =231±3.0

0 0 1